Generated: 19 April, 2024, 14:03

Sony BPS35A Series Laptop Service Center in Hyderabad Posted by sonyadmin - 14 Sep 2019 05:45

We offers all Kinds of computer peripherals chip level services. We are one of the leading motherboard chip level service centre in Hyderabad. We are servicing all kind of mother boards. We have been engaged in providing chip level service for many reputed clients across Hyderabad

Sony Laptop Service Center in Kukatpally

No.210B, Vijaya Sai Tower,

Second Floor, Viveknagar

Kukatpally, Hydeabad - 500072

Call: 040 48510111, 7997272463, 7997272205

Landmark: (opp to BJP Office / Above Reliance Digital)

Email:

This e-mail address is being protected from spambots. You need JavaScript enabled to view it

Sony Laptop Service Center in Gachibowli

Shop No 1 & 2, No 1-26/2 Basement Floor,

Gachibowli - Miyapur Road,

Gachibowli, Hyderabad

Telangana - 500032

Reach Us: 7331133305, 7331133306, 7331133307

Landmark: Opp Central Mall Behind TATA Motors

Kunena - Sony Service Centre Contact Details Generated: 19 April, 2024, 14:03

Email:
This e-mail address is being protected from spambots. You need JavaScript enabled to view it
Sony Laptop Service Center in Mandhapur
No. 1-99/14, 3rd Floor,
Hitech City Road, Madhapur Main Road,
Hyderabad, Telangana 500081
Reach us: 7331133301, 7331133302
Landmark: opp Fortune Towers, Behind State Bank of India
Email:
This e-mail address is being protected from spambots. You need JavaScript enabled to view it
We offer these chip level motherboard services at competitive prices as compared to other service providers in the market. We render motherboard chip level services for laptops of all brands, having the following defaults:
Sony Laptop Service center in Hyderabad
System dead.
No display.

Kunena - Sony Service Centre Contact Details Generated: 19 April, 2024, 14:03

System getting mute.
System getting hang.
Keyboard control section problem.
Memory control section problem.
Audio not working.
USB port not working.
Serial port not working.
CD Drive control section problem.
Hard disk control section problem.
Battery not charging.